









Number	Name from specification	Equipment type	Producer	Model and type	Current state of the equipment (Photos)	Mark of current state of the equipment	Notes	Production year or year of contract activation
10	Bandsaw Model MS 750, - manufacturer MK-ENGINEERING, production year 2013	Bandsaw	MK Engineering	MS 750		Good	Local company was hired to completely reparate the mechanism of these machinesm, and to adapt them in accordance to safety regulation. Machines are not reliable	2013
11		Bandsaw	MK Engineering	MS 750		Good		2013
12		Bandsaw	MK Engineering	MS 750		Good		2013
13	Scales for weighing and labelling of finished products with a long conveyor, - manufacturer DIBAL S3300	Label with automatic flow meter	Dibal	LS 3000	 	Bad		2006
14	Scales for weighing and labelling of finished products, - manufacturer DIBA, production year 2006	Label with automatic flow meter	Dibal	System 3300		Bad		2006
15	Stainless steel containers for fish preparing	Stainless steel containers for fish preparing	-	0,9 x 1,1 x 1 m ~ 1.000 lit.	  	Good	14 containers are upgraded with discharge valves, and are currently used for defrosting process. Remaining 28	2008
16	Measuring scale with sorting device, - manufacturer SCANVAEGT, production year 2006	Measuring scale with sorting device	Scanvaegt Systems	4717.275.10 4767.275.12		Good	Machine is in working condition. Not possible to calibrate and certify weighing unit of machine.	2006
17	Mussels and seashells measuring scale, - manufacturer SCANVAEGT	Mussels and seashells measuring scale	Scanvaegt Systems	-	 	Bad	Manufacturer plate is missing.	2006

23	Scale with sorter, - manufacturer SCANVAEGT, production year 2004	Scale with sorter	Scanvaegt Systems	7143.25.10.LR 7160.25.2x7 7112.25.10 LR		Good	weighing unit of machine is in good condition. Separator is in bad condition. Visible signs of transport damage, and	2002
42	Bandsaw - smaller, - manufacturer MK Engineering	Bandsaw - smaller	MK Engineering	-		Very good	Machine is in good condition.	2013
43	INOX filleting stations	INOX filleting stations	-	-		Very good	Stainless steel station, with 32 filleting points. Some adaptations needed to water installation. New plastic cutting boards needed. Off-site	2008
44	Waste belt	Waste belt for filleting station.	-	16 m		Very good	Waste belt for filleting station.	2008
45	Pisces head cutter machine, - manufacturer PISCES	Pisces head cutter machine	Pisces	-		Bad	Machine is in working condition.	2008
46	Filleting machine, - manufacturer PISCES FR 200	Filleting machine	Pisces	FR 200		Bad	Machine is in working condition.	2008
47	CRYOVAC model CJ52T LH, production year 2001	Packaging tunnel with thermo-foil	Cryovac AG	CJ52T LH		Bad		2001
48	DIVAPACK	Mašina za vakumsko pakovanje	Minipack Torre S.p.a	Divapack		Bad		2007
49	BELLINI & MEDA model BM 90 disimpilatore, production year 2007/2	Ispakivač	Bellini & Meda s.r.l.	BM 90		Bad	ULMA technician defined thismachines as part of ULMA Scorpius line.	2007

50	BELLINI & MEDA model BM 90 disimpilatore, production year	Ispakivač	Bellini & Meda s.r.l.	BM 90		Bad	ULMA technician defined this machines as part of ULMA Scorpius line.	2007
8	Instrument for measuring and analyses of air, - manufacturer IBERFLUID INSTRUMENTS, production year 2006	Instrument for measuring and analyses of air	Iberfluid Instruments	-		Very bad	Main door of machine is locked, and key is missing. Manufacturer plate is missing.	2006

Total initial tender price ~~333,530 €~~ 160,968 €

