




| R.b. | Naziv iz dostavljene specifikacije  | Vrsta opreme                       | Proizvođač               | Model i tipa | Trenutno stanje opreme na terenu 22.11.2018.   | Ocena trenutnog stanja opreme | Notes   | God. proiz. ili aktiv. |
|------|---|------------------------------------|--------------------------|--------------|--|-------------------------------|---|------------------------|
| 4    | Metal detektor sa transporterom, marke CINTEX   | Metal detektor                     | Cintex                   | CS 2060      |    | Dobro                         | Impossible to be calibrated. Companies Trim doo and Mos doo unsuccessfully tried to calibrate and certify the machine. Audits were passed with rented metal detector.                 | 2006                   |
| 18   | Higijenska stanica (za dezinfekciju ruku i cizama), marke STAR CLEAN, godina proizvodnje 2008 | Higijenska stanica za obuču i ruke | Star Clean               | 1600         |    | Veoma dobro                   | Main circuit board for one half of the machine is burned. New one will be printend and installed. A new pair of roller brushes also needed.   | 2008                   |
| 19   | Rashladni uredjaj   | Ledomat                            | ZIEGRA Eismaschinen GmbH | UBE 3500-2   |    | Dobro                         | From time to time machine is malfunctioning for unknown reasons. Companies Frigovent doo and Rotech EI were engaged to try to resolve this issue. Currently, machine is not reliable. | 2006                   |
| 21   | Transportne trake   | Transportne trake                  | -                        | -            | -  | Dobro                         |   | 2008                   |
| 22   | Podna vaga za palete, marke DIBAL   | Podna vaga                         | Dibal                    | -            | -  | Dobro                         | Machine is not complete. Only main steel frame was sent to Serbia.  | 2008                   |
| 25   | Boca vazdušnog kompresora, drobilica i mikser   | Drobilica                          | Gernal Menen             | NK 5 KL      |  | Loše                          | Visible signs of rust and transport damage. Inside mechanism of machines completely damaged.  | 1983                   |
| 26   |   | Vakumski mikser                    | Kilia                    | -            |  | Veoma loše                    |   | 1995                   |

|    |  |                                 |                        |         |  |   |             |   |      |
|----|--|---------------------------------|------------------------|---------|--|---|-------------|---|------|
| 28 | Sudopera od prohroma, marka ROSER                                    | INOX sudopera sa 4 slavine      | Roser                  | -       |    |   | Veoma dobro | <i>Sink is installed and in use. Another one needed. Offer requested from PakPromet.</i>  | 2008 |
| 31 | Transportne trake sa pripadajucim delovima, marke Ulma, Scanvaegt    | Trake za trakaste transportere  | Ulma+Scanvaegt Systems | -       |    |   | Dobro       | <i>Two chain transport bands are part of ULMA Scorpius line. Visible signs of heavy transport damage on both machines. Manufacturer plates missing.</i> | 2008 |
| 32 | Podna vaga za merenje paleta, marke DIBAL                            | Podna vaga                      | Dibal                  | -       |  |   | Dobro       | <i>Unable to be indentified.</i>  | 2007 |
| 33 | Ventilatori i kondenzatori, marke Wolf                               | Kaloriferi                      | Wolf                   | LH 25-3 |    |    | Loše        |   | 2008 |
| 34 |  | Kondezatori                     | -                      | -       |    |    | Veoma loše  |   | 2008 |
| 36 | Mašina za dekalifikaciju, godina proizvodnje 2013                    | Oprema za demineralizaciju vode | -                      | -       |    |   | Dobro       | <i>Signs of rust. Without any succes unit was tested. New one is bought and currently in use **Ova je i procenjena verovatno.</i>                       | 2013 |
| 37 | Postolje za vagu, marke DIBAL  | Postolje za vagu                | -                      | -       |    |   | Veoma dobro | <i>Three stainless steel stands, good condition, currently in</i>   | 2008 |
| 38 | Vaga sa štampancem, marke DIBAL                                      | Vaga sa štampancem              | Dibal                  | LP 3000 |   |   | Veoma loše  | <i>Without any succes, scales were tested by company Brotehna doo. It is impossible to calibrate and certify weighing units. Visible signs of rust.</i> | 2008 |
| 39 | Valjci rezervni - paket  | Valjci za transportnu traku     | -                      | -       |  |   | Dobro       |   | 2008 |
| 40 | Vaga marke ROBBE 9306  | Podna vaga                      | Robbe                  | 9306    |  |   | Dobro       |   | 2007 |
| 41 | Mašina za čišćenje cizama, marke Star clean, godina proizvodnje 2008 | Higijenska stanica za obuću     | Roser                  | 12480   |  |  | Dobro       | <i>Machine is in working condition.</i>   | 2008 |

|   |  |   |                     |             |  |  |            |   |      |
|---|--|---|---------------------|-------------|--|--|------------|---|------|
| 1 | Metal detektor marke DIBAL, godina proizvodnje 2006                            | Metal detektor                          | Dibal               | MD 3300     |   |  | Loše       | Visible signs of rust. Main circuit board burned.<br>Manufacturer plate missing | 2006 |
| 2 | Vaga sa monitorom i trakom, marke aew DELFORD SYSTEMS, godina proizvodnje 2001 | Vaga sa monitorom i transportnom trakom | AEW Delford Systems | INT Delford |   |  | Loše       |   | 2001 |
| 3 | Dodatna traka za veliku ribu, marke MK-ENGINEERING, godina proizvodnje 2007    | Transportna traka                       | MK Engineering      | -           |   |  | Veoma loše | To be assembled.  | 2007 |

**Ukupno početna cena opreme ~~68100 €~~ 47,670 €**

